




The diagram shows a cross-section of a window frame assembly. On the left, a vertical structure with horizontal lines represents the window pane or a support wall. To its right is a vertical frame element. A thick red vertical line is drawn along the interface between the pane and the frame. At the bottom of this frame element, there is a small red horizontal line. Two red arrows point from text boxes to these red markings. A third red arrow points from a text box to the bottom of the frame element.

Dein Plan Abdichtung:


Dichtungs Lücke
Nut im
Blendrahmen:
1. Haftfläche zu klein
für Silicon.
2. Auflagefläche zu
klein für
Komprieband.

Abdichtung fehlt:

Vorschlag
Hier Zusätzlich
Komprieband
einlegen.



Durchlaufende Abdichtung
Seitennasicht.



Draufsicht Durchlaufende Abdichtung
Fensterbank.

